

FIG. 1

W_k^N	N=4	N=8	N=16	N=32	N=64	N=128
k	0	0	0	0	0	0
					64	64
					32	32
					96	96
				16	16	16
					80	80
					48	48
					112	112
				8	8	8
					72	72
					40	40
					104	104
			8	24	24	24
					88	88
					56	56
					120	120
				4	4	4
					68	68
					36	36
					100	100
				20	20	20
					84	84
					52	52
					116	116
			4	12	12	12
					76	76
					44	44
					108	108
				28	28	28
					92	92
					60	60
					124	124

W_k^N	N=4	N=8	N=16	N=32	N=64	N=128
k	2	2	2	2	2	2
					66	66
					34	34
					98	98
				18	18	18
					82	82
					50	50
					114	114
			10	10	10	10
					74	74
					42	42
					106	106
				26	26	26
					90	90
					58	58
					122	122
			6	6	6	6
					70	70
					38	38
					102	102
				22	22	22
					86	86
					54	54
					118	118
			14	14	14	14
					78	78
					46	46
					110	110
				30	30	30
					94	94
					62	62
					126	126

W_k^N	N=4	N=8	N=16	N=32	N=64	N=128
k	1	1	1	1	1	1
					65	65
					33	33
					97	97
				17	17	17
					81	81
					49	49
					113	113
			9	9	9	9
					73	73
					41	41
					105	105
				25	25	25
					89	89
					57	57
					121	121
			5	5	5	5
					69	69
					37	37
					101	101
				21	21	21
					85	85
					53	53
					117	117
			13	13	13	13
					77	77
					45	45
					109	109
				29	29	29
					93	93
					61	61
					125	125

W_k^N	N=4	N=8	N=16	N=32	N=64	N=128
k	3	3	3	3	3	3
					67	67
					35	35
					99	99
				19	19	19
					83	83
					51	51
					115	115
			11	11	11	11
					75	75
					43	43
					107	107
				27	27	27
					91	91
					59	59
					123	123
			7	7	7	7
					71	71
					39	39
					103	103
				23	23	23
					87	87
					55	55
					119	119
			15	15	15	15
					79	79
					47	47
					111	111
				31	31	31
					95	95
					63	63
					127	127

FIG. 2




FIG. 3




FIG. 4